



HT-100/102/103/410/430/450/3200/3300

REPLACING THE CHAIR SIDE PANELS

To ensure that Human Touch® products are repaired in a manner that is fully consistent with the practices used during the manufacturing process, Human Touch requires that all product repairs are performed using only factory-new parts and in accordance with these product repair instructions.

SERVICE LEVEL: 1

1. Pull outward on the side panel to remove it from the chair base (Fig.1).
2. Align the plugs on the inside of the new side panel with the corresponding holes on the chair.
3. Push the new panel firmly into place (Fig.1).
4. Pull gently outward on the panel to ensure that it is secure.

